



Appendix A. Test Photos

1. Photographs of Conducted Emissions Test Configuration



Report No. : FR482634-02

FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A1 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01





Report No. : FR482634-02

SIDE VIEW


SPORTON INTERNATIONAL INC. Page No. : A2 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01




FCC Test Report

Report No. : FR482634-02

2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



FRONT VIEW



Page No.

Report Version

: A3 of A5

: Rev. 01

REAR VIEW


SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456




FCC Test Report

Report No. : FR482634-02

For radiated emissions 30MHz~1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : A4 of A5

Report Version


: Rev. 01




FCC Test Report

Report No. : FR482634-02

For radiated emissions above 1GHz



FRONT VIEW



REAR VIEW

SPORTON INTERNATIONAL INC. Page No. : A5 of A5
TEL: 886-3-327-3456 Report Version : Rev. 01