

## **Appendix II - Test Setup Photo**

Photo of radiated spurious emission






Report No.: TR-W1703-010 Page 1 of 3


ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 464-942

Report Form\_01 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800 http://www.the-eng.co.kr








Report No.: TR-W1703-010 Page 2 of 3

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 464-942

Report Form\_01 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800 http://www.the-eng.co.kr







Report No.: TR-W1703-010 Page 3 of 3

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 464-942

Report Form\_01 (Rev.0) http://www.the-eng.co.kr

TEL: +82-31-727-8300 FAX: +82-31-746-0800