Tune Up Procedure

Tune-up procedure

FM

Manufacturing tolerance

462.5625-462.7125			
Channel	Channel 1	Channel 4	Channel 7
Target (dBm)	28.0	28.0	28.0
Tolerance ±(dB)	1.0	1.0	1.0
467.5625-467.7125			
Channel	Channel 8	Channel 11	Channel 14
Target (dBm)	26.0	26.0	26.0
Tolerance ±(dB)	1.0	1.0	1.0
462.5500-462.7250			
Channel	Channel 15	Channel 19	Channel 22
Target (dBm)	28.0	28.0	28.0
Tolerance ±(dB)	1.0	1.0	1.0

Tune Up Procedure

- 1. RX Gain Calibration
- a. Put DUT in test mode
- b. Put DUT in BCH mode
- c. Put DUT in selected channel band
- d. Total gain chain calibration at center ARFCN
- e. Frequency Ripple calibration
- f. Complete RX_AGC Gain table
- 2. TX Power Calibration
- a. Put DUT in test mode
- b. Put DUT in BCH mode
- c. Put DUT in selected channel band
- d. Total gain chain calibration at center ARFCN
- e .Frequency Ripple calibration
- f .Complete TX_APC Gain table
- 3. AFC calibration
- a. Put DUT in test mode
- b. Put DUT in selected channel mode
- c. Calibration AFC at center ARFCN
- d. Complete AFC result table