APRIX LATINOAMERICA S.A.

Federal Communications Commission Equipment Autorisation Division 7435 Oakland Mills Road Columbia, MD 21046

Class II permissive change Request

Model No.: Aprix Tab64C,Aprix Tab64A, Aprix Tab64B,Aprix Tab64D,Aprix Tab64E, 64A,64B,64C,64D,64E,A10,A101,B10,B101, APT10, APT101, AX10,BX10 etc., FCC ID: 2AHJQ-APT67A, Granted on 18/07/2017

To Whom it may concern:

Pursuant to CFR § 2.1043, APRIX LATINOAMERICA S.A.hereby requests a Class II permissive change

Reason:

The product has below changes:

- 1) RAM change from 2G+64G to 2G+32G
- 2) mainboard increase HDMI port

Client's signature:

(n 60

Client's name / title: Coco Ren / Manager

Tel: 86-0755-23014423

Email: coco@aprix.com.cn

2017-7-11