US Tech Test Report: FCC ID: IC: Test Report Number:

Issue Date: Customer: Model: FCC Part 15 Certification 2AHPM-TITAN 21163-TITAN 16-0184 August 29, 2016 HDJ WIRELESS ENTERPRISE LLC VERSA ROUTER 1100 TITAN

TEST CONFIGURATION PHOTOGRAPHS




Figure 1. Radiated Emissions Test Setup, BiCon 30-200 MHz

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification 2AHPM-TITAN 21163-TITAN 16-0184 August 29, 2016 HDJ WIRELESS ENTERPRISE LLC VERSA ROUTER 1100 TITAN




Figure 2. Radiated Emissions Test Setup, Log Periodic 200-1000 MHz

US Tech Test Report:
FCC ID:
IC:
Test Report Number:
Issue Date:
Customer:
Model:

FCC Part 15 Certification 2AHPM-TITAN 21163-TITAN 16-0184 August 29, 2016 HDJ WIRELESS ENTERPRISE LLC VERSA ROUTER 1100 TITAN




Figure 4. Radiated Emissions Test Setup, Horn above 1 GHz

US Tech Test Report:
FCC ID:
CC Part 15 Certification
CAL ID:
CC ID:
CC



Figure 5. Power Line Conducted Emissions