Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 1 of 3
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01

Report No.: FR631725-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3





Rear View



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 2 of 3
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01

Report No.: FR631725-01B


Report Template No.: BU5-FR15CBT4.0 Version 1.3

<Radiated Emission>

LF



HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 3 of 3
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01

Report No. : FR631725-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3