

Report No.: FR631725-01C

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 1 of 4

Report Issued Date : Jul. 01, 2016

Report Version : Rev. 01





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 2 of 4
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01




Report No. : FR631725-01C


<Radiated Emission>

Ant. 1

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 3 of 4
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01




Report No.: FR631725-01C

Ant. 2

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 4 of 4
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01