

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 1 of 4
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01

Report No.: FR631725-01D

Report Template No.: BU5-FR15EWL MA Version 1.4



Report No.: FR631725-01D



Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 2 of 4
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15EWL MA Version 1.4



<Radiated Emission>

Ant. 1

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 3 of 4
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL MA Version 1.4


Report No.: FR631725-01D




Report No.: FR631725-01D

Ant. 2

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHSE-2045 Page Number : 4 of 4
Report Issued Date : Jul. 01, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL MA Version 1.4