

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 1 of 5
Report Issued Date : May 07, 2018
Report Version : Rev. 01

Report No.: FR741112-01D

Report Template No.: BU5-FR15EWL AC Version 2.0





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 2 of 5
Report Issued Date : May 07, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0

Report No.: FR741112-01D




<Ant. 1>

<Radiated Emission>

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 3 of 5
Report Issued Date : May 07, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0

Report No.: FR741112-01D




<Ant. 2>

LF







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 4 of 5 Report Issued Date: May 07, 2018 Report Version : Rev. 01


Report No.: FR741112-01D

Report Template No.: BU5-FR15EWL AC Version 2.0




MIMO <Ant. 1 + 2>

LF







TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 5 of 5
Report Issued Date : May 07, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0

Report No.: FR741112-01D