3. Internal Photograph of EUT

Model Name: QX91KB

Report No.: EP741112-01

QX91KA




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 8 of 15

Report Issued Date : May 31, 2018
Report Version : Rev. 01

Report No.: EP741112-01

QX91KA




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 9 of 15

Report Issued Date : May 31, 2018 Report Version : Rev. 01



Report No.: EP741112-01

QX91KA




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 10 of 15 Report Issued Date : May 31, 2018

: Rev. 01 Report Version

Report No.: EP741112-01

QX91KA




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 11 of 15 Report Issued Date : May 31, 2018

Report No.: EP741112-01

Model Name: QX91KB


QX91KA



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 12 of 15
Report Issued Date : May 31, 2018



QX91KA




TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 13 of 15 Report Issued Date : May 31, 2018



Report No.: EP741112-01


QX91KA



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 14 of 15 Report Issued Date : May 31, 2018



QX91KA



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUD-3819 Page Number : 15 of 15
Report Issued Date : May 31, 2018