

Report No.: FR651909-01B

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUE-9536 Page Number : 1 of 4 Report Issued Date: Mar. 14, 2017 Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUE-9536 Page Number : 2 of 4
Report Issued Date : Mar. 14, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3




<Ant. 1>


<Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUE-9536 Page Number : 3 of 4
Report Issued Date : Mar. 14, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3

Report No.: FR651909-01B




<Ant. 2>


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUE-9536 Page Number : 4 of 4
Report Issued Date : Mar. 14, 2017
Report Version : Rev. 01

Report No.: FR651909-01B

Report Template No.: BU5-FR15CWL Version 1.3