

Setup Photographs

<Conducted Emission> Mode 2



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUE-3937 Page Number : 1 of 3
Report Issued Date : Dec. 13, 2016
Report Version : Rev. 01

Report No.: FR651909-01A

Report Template No.: BU5-FR15CBT4.0 Version 1.3





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUE-3937 Page Number : 2 of 3
Report Issued Date : Dec. 13, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT4.0 Version 1.3




Report No.: FR651909-01A

<Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUE-3937 Page Number : 3 of 3
Report Issued Date : Dec. 13, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3