

# Report No.: FR693034-02C

# **Setup Photographs**

# <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 1 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CZigbee Version 1.0





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 2 of 3 Report Issued Date: May 15, 2017 Report Version : Rev. 01

Report No.: FR693034-02C

Report Template No.: BU5-FR15CZigbee Version 1.0




## Report No.: FR693034-02C


#### <Radiated Emission>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 3 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CZigbee Version 1.0