

# **Setup Photographs**

## <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 1 of 3

Report Issued Date : May 15, 2017

Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0

Report No.: FR693034-02E



Report No.: FR693034-02E



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 2 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0



### Report No.: FR693034-02E


### <Radiated Emission>

#### Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 3 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0