

## Report No. : FR693034-02A

# **Setup Photographs**

## <Conducted Emission>



Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 1 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0





Rear View


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 2 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0




### Report No.: FR693034-02A

### <Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 3 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0