

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 1 of 4
Report Issued Date : May 26, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0

Report No.: FR693034-02F







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 2 of 4
Report Issued Date : May 26, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0



Report No.: FR693034-02F


<Radiated Emission>

Y Plane for 03CH11-HY

LF



HF



SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 3 of 4
Report Issued Date : May 26, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0

Report No.: FR693034-02F

Y Plane for 03CH12-HY

HF



TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 4 of 4
Report Issued Date : May 26, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWL AC Version 2.0