

## **Setup Photographs**

## <Conducted Emission>



Remote View


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 1 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01

Report No.: FR693034-02B

Report Template No.: BU5-FR15CBT4.0 Version 1.3





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 2 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT4.0 Version 1.3




Report No.: FR693034-02B

## <Radiated Emission>

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHUF-6294 Page Number : 3 of 3
Report Issued Date : May 15, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3