INTERTEK TESTING SERVICE

Report No.: 16090904HKG-003

Equipment Photographs

Model: 530000A

(Internal)





FCC ID: 2AHUVHCR0004


INTERTEK TESTING SERVICE

Report No.: 16090904HKG-003

Equipment Photographs

Model: 530000A

(Internal)





FCC ID: 2AHUVHCR0004


INTERTEK TESTING SERVICE

Report No.: 16090904HKG-003

Equipment Photographs

Model: 530000A

(Internal)





FCC ID: 2AHUVHCR0004