JOYAUDIO CO., LIMITED

FCC ID: 2AHWN-W1506D

October 12,2016-10-12 Federal Communications Commission Authorization and Evaluation Division 7435 Oakland Mills Road Columbia MD 21046

I would like to confirm this device(FCC ID: 2AHWN-W1506D)does not have tune up information because the tune up is fixed by the manufacturer. Therefore, the user cannot tune up the device.

Sincerely,
JOYAUDIO CO., LIMITED

Yongbao Wu

Manager