Setup Photographs

<Conducted Emission>

Mode 2



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHXB-4396 Page Number : 1 of 4 Report Issued Date: Mar. 10, 2017 Report Version : Rev. 01

Report No. : FR662707-01B

Report No. : FR662707-01B



Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHXB-4396 Page Number : 2 of 4
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

<Radiated Emission>


<Ant. 1>

Y Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHXB-4396 Page Number : 3 of 4
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report No. : FR662707-01B


C Test Report No.: FR662707-01B

<Ant. 2>

Z Plane







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHXB-4396 Page Number : 4 of 4
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01