Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHXE-5310 Page Number : 1 of 4
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL AC MA Version 1.4

Report No. : FR651918-03E





Rear View



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHXE-5310 Page Number : 2 of 4
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01
Report Template No.: BU5-FR15EWL AC MA Version 1.4

Report No. : FR651918-03E




<Radiated Emission>

Bottom Side

LF







SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHXE-5310 Page Number : 3 of 4
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report No. : FR651918-03E

Report Template No.: BU5-FR15EWLAC MA Version 1.4




Report No. : FR651918-03E

Rear Side

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AHXE-5310 Page Number : 4 of 4
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLAC MA Version 1.4