Test Report No: 11185297S-A

# **APPENDIX 3: Photographs of test setup**

### **Radiated emission**






## UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN


Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401

Test Report No: 11185297S-A

#### Pre-check of the worst case







# UL Japan, Inc. Shonan EMC Lab.


1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN Telephone : +81 463 50 6400

Telephone +81 463 50 6401 Facsimile


Test Report No: 11185297S-A

#### Pre-check of the worst case





Mechanical Key (inserted) \* Worst



**END OF REPORT** 

## UL Japan, Inc. Shonan EMC Lab.

1-22-3 Megumigaoka, Hiratsuka-shi, Kanagawa-ken, 259-1220 JAPAN

Telephone : +81 463 50 6400 Facsimile : +81 463 50 6401