

Photo 8



Photo 9





Photo 10





Photo 11



FCC Report Tel: 400-788-9558 0755-33019988 Web:Http://www.bctc-lab.com.cn Page6 of 13



Photo 12





Photo 13



FCC Report

Tel: 400-788-9558

0755-33019988

Web:Http//www.bctc-lab.com.cn



Photo 14





Photo 15



FCC Report Tel: 400-788-9558 0755-33019988 Web:Http://www.bctc-lab.com.cn Page8 of 13




Photo 16

Antenna location



Photo 17



FCC Report Tel: 400-788-9558 0755-33019988 Web:Http//<u>www.bctc-lab.com.cn</u> Page9 of 13



Photo 18





Photo 19



FCC Report

Tel: 400-788-9558

0755-33019988

Web:Http//www.bctc-lab.com.cn








Photo 21





Photo 22




Photo 23

