USB Port Statement

FCC ID: 2AIAT16808 Date: May 10, 2016

To whom it may concern:

We, the undersigned, state that the device's
Models Name: MI-SPB57-101, MI-SPB57-652, MI-SPB57-400, MI-SPB63-101,
MI-SPB63-125, MI-SPB56-101, MI-SPB56-600, MI-SPB56-400,
BT422, JK201, JK202, S08, S09, C6, AS101, AS102, AS103, AS107,
AS108, AS109, A19, A30, A32, A35, A36, A52, A55, A60, A80, A5, A50,
A223, Q9, Q96, AK108, AK201, AK202, HyperGear Rave, B13, AS201,
AS202, AS203, AS205, AS206, AK109, BT06, AK205, AK206, AK203,
A33, A56, AK101, AK301, AK102, AK209, S11, S12, AS320, AS1032,
X3, AK204, A17, S13, AS81, A28, AK207, AK208, AS104, 21565,
RD-2001, RD-2009, RD-2020, RD-2035, RD-2032, RD-2007
USB port only used for charge, no any data transfer to PC.

Sincerely,

Clina Ma/Manager

ma Ma