
3. Internal Photograph of EUT


Brand Name: country wireless; Model Name: CW5100

Report No.: EP652611




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 10 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01

Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 11 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01


Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 12 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01




Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100


: 13 of 29 Page Number Report Issued Date : Aug. 01, 2016 Report Version : Rev. 01





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 14 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01


Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 15 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01



Report No.: EP652611




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100

: 16 of 29 Page Number Report Issued Date : Aug. 01, 2016 Report Version : Rev. 01

Brand Name: country wireless; Model Name: CW5100

Report No.: EP652611




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100

Page Number : 17 of 29 Report Issued Date : Aug. 01, 2016 Report Version : Rev. 01




Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100

Page Number : 18 of 29 Report Issued Date : Aug. 01, 2016 Report Version : Rev. 01

Report No.: EP652611




Brand Name: country wireless; Model Name: CW5100

SPORTON INTERNATIONAL (SHENZHEN) INC.

TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 19 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01


Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 20 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01



Report No.: EP652611




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100

: 21 of 29 Page Number Report Issued Date : Aug. 01, 2016 Report Version : Rev. 01




Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100



Report No.: EP652611




TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100

: 23 of 29 Page Number Report Issued Date : Aug. 01, 2016 Report Version : Rev. 01




Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100


Page Number : 24 of 29 Report Issued Date : Aug. 01, 2016 Report Version : Rev. 01

Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 25 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01


Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 26 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01



Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 27 of 29 Report Issued Date : Aug. 01, 2016 Report Version : Rev. 01

Report No.: EP652611



TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 28 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01





TEL: 86-755-8637-9589 FAX: 86-755-8637-9595 FCC ID: 2AICPCW5100 Page Number : 29 of 29
Report Issued Date : Aug. 01, 2016
Report Version : Rev. 01