




170014_35.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F170014E2

 Date of issue:
 11.09.2017
 Order No.:
 17-110014
 page 1 of 9






170014_39.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F170014E2

 Date of issue:
 11.09.2017
 Order No.:
 17-110014
 page 2 of 9





170014_36.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F170014E2

 Date of issue:
 11.09.2017
 Order No.:
 17-110014
 page 3 of 9






170014_37.JPG: Test setup - radiated test on open area test site

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F170014E2

 Date of issue:
 11.09.2017
 Order No.:
 17-110014
 page 4 of 9






170014_38.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F170014E2

 Date of issue:
 11.09.2017
 Order No.:
 17-110014
 page 5 of 9






170014_40.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F170014E2

 Date of issue:
 11.09.2017
 Order No.:
 17-110014
 page 6 of 9






170014_41.JPG: Test setup – radiated test in anechoic chamber

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F170014E2

 Date of issue:
 11.09.2017
 Order No.:
 17-110014
 page 7 of 9






170014_42: Test setup – conducted emissions on power supply lines

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F170014E2

 Date of issue:
 11.09.2017
 Order No.:
 17-110014
 page 8 of 9





170014_44: Test setup – conducted measurements at antennaport

 Examiner:
 Paul NEUFELD
 Test Report No.:
 F170014E2

 Date of issue:
 11.09.2017
 Order No.:
 17-110014

page 9 of 9