


160903\_01: Test setup - Radiated emission anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 1 of 6






160903\_02: Test setup - Radiated emission anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 2 of 6





160903\_03: Test setup - Radiated emission anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 3 of 6






160903\_04: Test setup - Radiated emission anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 4 of 6





160903\_05: Test setup - Radiated emission anechoic chamber

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 5 of 6





160903\_13: Test setup – conducted emissions on power supply lines

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 6 of 6