


160903\_20.jpg: EUT on carrier board - top view

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 1 of 4






160903\_21.jpg: Close-up of the EUT on the carrier board – top view

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 2 of 4






160903\_22.jpg: Close-up of the EUT without shielding - top view

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 3 of 4





160903\_23.jpg: Carrier board – bottom view

 Examiner:
 Paul NEUFELD
 Report Number:
 E160902E1

 Date of issue:
 13.09.2016
 Order Number:
 16-110902
 page 4 of 4