


Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP3-8320 Page Number : 1 of 3
Report Issued Date : Nov. 15, 2016
Report Version : Rev. 01

Report No.: FR670616-01D

Report Template No.: BU5-FR15EWL Version 1.4





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP3-8320 Page Number : 2 of 3
Report Issued Date : Nov. 15, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15EWL Version 1.4




<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP3-8320 Page Number : 3 of 3
Report Issued Date : Nov. 15, 2016
Report Version : Rev. 01

Report No.: FR670616-01D

Report Template No.: BU5-FR15EWL Version 1.4