


## Report No. : FR670616-01B

# **Setup Photographs**

## <Conducted Emission>



Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP3-8320 Page Number : 1 of 3
Report Issued Date : Nov. 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP3-8320 Page Number : 2 of 3
Report Issued Date : Nov. 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3




# Report No. : FR670616-01B


### <Radiated Emission>

#### **Z** Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP3-8320 Page Number : 3 of 3
Report Issued Date : Nov. 11, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CWL Version 1.3