


Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP3-8320 Page Number : 1 of 3
Report Issued Date : Nov. 25, 2016
Report Version : Rev. 01

Report No.: FR670616-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3



Report No.: FR670616-01B



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP3-8320 Page Number : 2 of 3
Report Issued Date : Nov. 25, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3




Report No.: FR670616-01B


<Radiated Emission>

Z Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP3-8320 Page Number : 3 of 3
Report Issued Date : Nov. 25, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT4.0 Version 1.3