

## Setup Photographs

## <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP4-4639 Page Number : 1 of 3
Report Issued Date : Dec. 13, 2016
Report Version : Rev. 01

Report No.: FR671335-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3



Report No.: FR671335-01B



Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP4-4639 Page Number : 2 of 3
Report Issued Date : Dec. 13, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT4.0 Version 1.3




## <Radiated Emission>

## X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP4-4639 Page Number : 3 of 3
Report Issued Date : Dec. 13, 2016
Report Version : Rev. 01

Report No.: FR671335-01B

Report Template No.: BU5-FR15CBT4.0 Version 1.3