

Setup Photographs

<Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.


TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP4-4639 Page Number : 1 of 3
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report No.: FR671335-01E

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5







Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP4-4639 Page Number : 2 of 3
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5




Report No.: FR671335-01E


<Radiated Emission>

X Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP4-4639 Page Number : 3 of 3
Report Issued Date : Jan. 23, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC MA Version 1.5