

## Report No.: FR671335-01A

# **Setup Photographs**

# <Conducted Emission>



Remote View

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP4-4639 Page Number : 1 of 3
Report Issued Date : Dec. 13, 2016
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 1.1





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP4-4639 Page Number : 2 of 3
Report Issued Date : Dec. 13, 2016
Report Version : Rev. 01


Report Template No.: BU5-FR15CBT Version 1.1

<Radiated Emission>




### X Plane

LF



HF



# SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP4-4639 Page Number : 3 of 3
Report Issued Date : Dec. 13, 2016
Report Version : Rev. 01

Report No.: FR671335-01A

Report Template No.: BU5-FR15CBT Version 1.1