

# **Setup Photographs**

## <Conducted Emission>



Remote View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP5-3975 Page Number : 1 of 3
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC Version 1.5

Report No.: FR671336-01E





Rear View

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP5-3975 Page Number : 2 of 3
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report No. : FR671336-01E

Report Template No.: BU5-FR15EWLB4 AC Version 1.5




#### Report No.: FR671336-01E

### <Radiated Emission>

#### **Z** Plane

LF



HF



SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-328-4978 FCC ID: 2AIP5-3975 Page Number : 3 of 3
Report Issued Date : Mar. 10, 2017
Report Version : Rev. 01

Report Template No.: BU5-FR15EWLB4 AC Version 1.5