

Diversity MB, HB Antenna

TEL: 886-3-327-3456 Page Number : 57 of 67
FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018




TEL: 886-3-327-3456 Page Number : 58 of 67
FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018





TEL: 886-3-327-3456 Page Number : 59 of 67
FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018




TEL: 886-3-327-3456 Page Number : 60 of 67
FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018



Brand Name: SIRIN LABS / Model Name: SR00300-W

Report No.: EP8O0518




TEL: 886-3-327-3456 Page Number : 61 of 67 FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018




Brand Name: SIRIN LABS / Model Name: SR00300-W


Report No.: EP8O0518



TEL: 886-3-327-3456 Page Number : 62 of 67 FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018



TEL: 886-3-327-3456 Page Number : 63 of 67
FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018




TEL: 886-3-327-3456 Page Number : 64 of 67
FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018

TEL: 886-3-327-3456 Page Number : 65 of 67
FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018



Brand Name: SIRIN LABS / Model Name: SR00300-W


Report No.: EP8O0518



TEL: 886-3-327-3456 Page Number : 66 of 67 FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018

: 01 Report Version

Report No.: EP8O0518



\_\_\_\_\_THE END\_\_\_\_

TEL: 886-3-327-3456 Page Number : 67 of 67
FAX: 886-3-328-4978 Issued Date : Nov. 19, 2018