


## **Appendix Test Setup Photo**

Photo of radiated spurious emission








Report No.: TR-W1803-014 Page 1 of 3

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

Report Form\_01 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800 http://www.the-eng.co.kr







18 GHz - 26 GHz



Report No.: TR-W1803-014 Page 2 of 3

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813


Report Form\_01 (Rev.0)


TEL: +82-31-727-8300 FAX: +82-31-746-0800

http://www.the-eng.co.kr



Photo of AC power line conducted emission







Report No.: TR-W1803-014 Page 3 of 3

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

Report Form\_01 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800 http://www.the-eng.co.kr