


Appendix Test Setup Photo

Photo of radiated spurious emission





Report No.: TR-W1708-008 Page 1 of 3


ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

Report Form_01 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800

http://www.the-eng.co.kr





Report No.: TR-W1708-008 Page 2 of 3

FAX: +82-31-746-0800


ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813


TEL: +82-31-727-8300

Report Form_01 (Rev.0) http://www.the-eng.co.kr



Photo of AC power line conducted emission





Report No.: TR-W1708-008 Page 3 of 3

ENG Co., Ltd. 135-60 Gyeongchung-daero, Gonjiam-eup, Gwangju-si, Gyeonggi-do, Korea 12813

Report Form_01 (Rev.0)

TEL: +82-31-727-8300 FAX: +82-31-746-0800 http://www.the-eng.co.kr