


1. Photographs of Conducted Emissions Test Configuration



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F1 of F5

Report Version





Side view

SPORTON INTERNATIONAL INC. Page No. : F2 of F5
TEL: 886-3-327-3456 Report Version : Rev. 01


FAX: 886-3-327-0973



## 2. Photographs of Radiated Emissions Test Configuration For radiated emissions 9kHz~30MHz



Front view



Rear view

SPORTON INTERNATIONAL INC. TEL: 886-3-327-3456


FAX: 886-3-327-0973

Page No. : F3 of F5


Report Version



## For radiated emissions 30MHz~1GHz



Front view



Rear view


SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F4 of F5

Report Version



## For radiated emissions above 1GHz



Front view



Rear view

SPORTON INTERNATIONAL INC.

TEL: 886-3-327-3456 FAX: 886-3-327-0973 Page No. : F5 of F5

Report Version