


# Appendix D. Setup Photographs

# <Conducted Emission>

#### Mode 1





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AIZN-X604 Page Number : D1 of D2
Report Issued Date May 04, 2018
Report Version : Rev. 01

Report No.: FR830917A

Report Template No.: BU5-FR15CBT Version 2.0



## <Radiated Emission>

### **Z** Plane

LF





Sporton International (Kunshan) Inc.

TEL: +86-512-57900158 FAX: +86-512-57900958 FCC ID: 2AIZN-X604 Page Number : D2 of D2
Report Issued Date May 04, 2018
Report Version : Rev. 01
Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR830917A