


# Appendix E. Setup Photographs

# <Conducted Emission> Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : E1 of E3
Report Issued Date Apr. 19, 2018
Report Version : Rev. 01

Report No.: FR830209C

Report Template No.: BU5-FR15CWL AC MA Version 2.0




## <Radiated Emission>

### **Z** Plane

30MHz ~ 1GHz



1GHz ~ 18GHz




Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : E2 of E3
Report Issued Date Apr. 19, 2018
Report Version : Rev. 01

Report No.: FR830209C

Report Template No.: BU5-FR15CWL AC MA Version 2.0

### 18GHz ~ 40GHz



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : E3 of E3
Report Issued Date Apr. 19, 2018
Report Version : Rev. 01

Report No.: FR830209C

Report Template No.: BU5-FR15CWL AC MA Version 2.0