
## Appendix D. Setup Photographs

## <Conducted Emission> Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X622 Page Number : D1 of D2
Report Issued Date Aug. 03, 2018
Report Version : Rev. 01


Report No.: FR861105A

Report Template No.: BU5-FR15CBT Version 2.0


## <Radiated Emission>

## **Z** Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X622 Page Number : D2 of D2
Report Issued Date Aug. 03, 2018
Report Version : Rev. 01

Report No.: FR861105A

Report Template No.: BU5-FR15CBT Version 2.0