

# Appendix A. Setup Photographs

### <Conducted Emission>

#### Mode 5





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : A1 of A2
Report Issued Date : Apr. 19, 2018
Report Version : Rev. 01

Report No.: FC830209

Report Template No.: BU5-FD15B Version 1.3


## <Radiated Emission>

#### Mode 4

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : A2 of A2
Report Issued Date : Apr. 19, 2018
Report Version : Rev. 01

Report Template No.: BU5-FD15B Version 1.3

Report No.: FC830209