


## Appendix E. Setup Photographs

## <Conducted Emission> Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X604 Page Number : E1 of E2
Report Issued Date May 04, 2018
Report Version : Rev. 01

Report No.: FR830917C

Report Template No.: BU5-FR15CWL Version 2.0




## <Radiated Emission>

## **Z** Plane

LF





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X604 Page Number : E2 of E2
Report Issued Date May 04, 2018
Report Version : Rev. 01

Report No.: FR830917C

Report Template No.: BU5-FR15CWL Version 2.0