
Appendix E. Setup Photographs

<Conducted Emission> Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X5515 Page Number : E1 of E2
Report Issued Date Jul. 11, 2018
Report Version : Rev. 01

Report Template No.: BU5-FR15CBT Version 2.0

Report No.: FR851121A


<Radiated Emission>

X Plane

LF



HF



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X5515 Page Number : E2 of E2
Report Issued Date Jul. 11, 2018
Report Version : Rev. 01

Report No.: FR851121A

Report Template No.: BU5-FR15CBT Version 2.0