


Appendix E. Setup Photographs

<Conducted Emission> Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : E1 of E3
Report Issued Date Apr. 19, 2018
Report Version : Rev. 01

Report No.: FR830209B


Report Template No.: BU5-FR15CBT4.0 Version 2.0




<Radiated Emission>

Z Plane

30MHz ~ 1GHz



1GHz ~ 18GHz



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : E2 of E3
Report Issued Date Apr. 19, 2018
Report Version : Rev. 01

Report No.: FR830209B

Report Template No.: BU5-FR15CBT4.0 Version 2.0



18GHz ~ 40GHz



Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : E3 of E3
Report Issued Date Apr. 19, 2018
Report Version : Rev. 01

Report No.: FR830209B

Report Template No.: BU5-FR15CBT4.0 Version 2.0