

# Appendix D. Setup Photographs

# <Conducted Emission> Mode 1





Sporton International (Shenzhen) Inc.

TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : D1 of D3
Report Issued Date Apr. 19, 2018
Report Version : Rev. 01

Report No.: FR830209A

Report Template No.: BU5-FR15CBT Version 2.0




## <Radiated Emission>

### **Z** Plane

30MHz ~ 1GHz



1GHz ~ 18GHz



Sporton International (Shenzhen) Inc.


TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : D2 of D3
Report Issued Date Apr. 19, 2018
Report Version : Rev. 01

Report No.: FR830209A

Report Template No.: BU5-FR15CBT Version 2.0



### 18GHz ~ 40GHz



TEL: +86-755-8637-9589 FAX: +86-755-8637-9595 FCC ID: 2AIZN-X608 Page Number : D3 of D3
Report Issued Date Apr. 19, 2018
Report Version : Rev. 01

Report No.: FR830209A

Report Template No.: BU5-FR15CBT Version 2.0