

Annex 2: External photographs of EUT to TEST REPORT

No.: 16-1-0188601T01a

According to:

FCC Regulations

Part 15.205 Part 15.209 Part 15.407

for

Intel Corporation

VLMTX58G Video Link Module TX 5.8GHz + WALSIN PCB ANTENNA RFPCA201018IM5B301 (2 pcs)

FCC-ID: 2AJ2A-VLMTX58G







TABLE OF CONTENTS:

I. EXTERNAL PHOTOGRAPHS	3
1.1. Equipment Under Test (EUT)	-
1.2. Auxiliary Equipment (AE)	
1.3. Test Software Screenshots	




1. External photographs

1.1. Equipment Under Test (EUT)




Photograph 1: Overview VLMTX58G + WALSIN ANTENNA + WALSIN ANTENNA




Photograph 2: VLMTX58G-Front side view with Antenna port 0 & Port 1






Photograph 3: VLMTX58G-Back side view




Photograph 4: VLMTX58G-Left side view





Photograph 5: VLMTX58G-Right side view



Photograph 6: WALSIN ANTENNA + WALSIN ANTENNA



1.2. Auxiliary Equipment (AE)



Photograph 7: AE1-Test Tablet- Front side



Photograph 8: AE1-Test Tablet- Back side






Photograph 9: AE1-Test Tablet- sTest USB Port View



1.3. Test Software Screenshots




Photograph 10: Test Software AppCom-Version 4.0.4.26 Software




Photograph 11: Test Software AppCom-Version 4.0.4.26 Software





Photograph 12: U-NII-1|U-NII-2A|U-NII-2C| U-NII 3-Frequency Channel Scripts



Photograph 13: U-NII-1|U-NII-2A|U-NII-2C| U-NII 3-+10dBm Power Setting Script