

182138\_Ext1: EUT front view

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 1 of 8





182138\_Ext2: EUT bottom view

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138






182138\_Ext3: EUT back view

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 3 of 8





182138\_Ext4: EUT top view

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138

 page 4 of 8
 page 4 of 8






182138\_Ext5: EUT side view 1

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138

 page 5 of 8
 page 5 of 8






182138\_Ext6: EUT side view 2

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 6 of 8



Annex B: EUT External Photos




182138\_Ext7: EUT 3D view 1

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 7 of 8



Annex B: EUT External Photos



182138\_Ext8: EUT 3D view 2

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138