




182138_Set12.JPG: Test setup shielded room M4

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 1 of 6





182138_Set3.JPG: Test setup anechoic chamber M20, 9 kHz - 30 MHz

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 2 of 6





182138_Set9.JPG: Test setup open area test site, 9 kHz - 30 MHz @ 3m

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 3 of 6






182138_Set10.JPG: Test setup open area test site, 9 kHz - 30 MHz @ 10m

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 4 of 6






182138_Set8.JPG: Test setup anechoic chamber M20, 30 MHz - 1 GHz

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 5 of 6





182138_Set11.JPG: Test setup open area test site M6, 30 MHz - 1 GHz

 Examiner:
 Ruben BRAUN
 Report Number:
 F182138E2

 Date of issue:
 25.02.2019
 Order Number:
 18-112138
 page 6 of 6